



UNITED STATES DEPARTMENT OF COMMERCE
Patent and Trademark Office
ASSISTANT SECRETARY OF COMMERCE AND
COMMISSIONER OF PATENTS AND TRADEMARKS
P.O. Box 1450
Alexandria, VA 22313-1450

March 26, 2008

WESTERMAN, HATTORI, DANIELS & ADRIAN, LLP

1250 CONNECTICUT AVENUE, NW

SUITE 700

WASHINGTON DC 20036

Patent No. : 7,207,767 B2
Inventor(s) : Kosuke Ashihara, et al.
Issued : April 24, 2007
For INDUCER, AND INDUCER-EQUIPPED
PUMP
Doc. No. 043183

To Whom It May Concern:

The Certificate of Correction issued on March 18, 2008, issued in error, in that error(s) was made in identifying the patent number and/or keying text/corrections, i.e.:

In the issued certificate of correction, the correction to change the title should have also been listed to be incorporated at Column 1, line 1. A superseding cofc will be issued to include the change of the title to occur at Column 1, line 1.

Therefore, a certificate of correction will be issued to correct (supersede) the Certificate of Correction containing error(s), made during preparation of the Certificate of Correction, as noted above.

No further response is required, from applicants (attorney). However, errors discovered by attorney, other than as noted and described above, should be noted on *a copy* of the Certificate of Correction that was issued in error, accompanied by a signed transmittal letter and submitted directed to this Branch.

Antonio Johnson
(703) 308-9390 ext. 111
For Cecelia Newman, Supervisor
Decisions & Certificates of Correction Branch
(703) 305-8309 / 703-308-9390 ext. 102
cbn